



2018 Mitsubishi Vehicle Diagnostic Report

Vehicle Information

2018 / Mitsubishi / OUTLANDER (GF#) /
 VIN: JE4LZ21W3JZ701717

Odometer Reading: 208480km
 License Plate: 31358/Y



Scan to download PDF

Customer Information

Name: ministry

Device information

Scanner: MaxiSys MS909
 Version: V3.00

Serial Number: V19GN5C01153
 Repair Order Number: V19GN5C0115320240430083340575

System Scanned (15)

System	Status/DTC
MPI/GDI/Diesel	1
AT/CVT/A-MT/TC-SST	0
ABS/ASC/ASTC/WSS	0
SRS-Air Bag	0
Meter	0
TPMS - without KOS	3
Air Conditioner	0
Auto Cruise	0
4WS/Electric Power Steering	0
ETACS	3
KOS/IMMO/Keyless - IMMOBI & Keyless	3
Steering Angle Sensor	0
AUDIO - CD AUDIO	0
Corner Sensor/Sonar	0
AWC	0

DTC (10)

MPI/GDI/Diesel (1 DTC)



DTC	Description	Status
P0421	Warm up catalyst deterioration 1	Stored DTC

TPMS - without KOS (3 DTCs)

DTC	Description	Status
C1912	Tyre air pressure low, Tyre1	Stored DTC
C1931	Tyre ID reception fail, Tyre3	Active DTC
C1932	Tyre air pressure low, Tyre3	Stored DTC

ETACS (3 DTCs)

DTC	Description	Status
C1912	Tyre air pressure low, Tyre1	Stored DTC
C1931	Tyre ID reception fail, Tyre3	Active DTC
C1932	Tyre air pressure low, Tyre3	Stored DTC

KOS/IMMO/Keyless - IMMOBI & Keyless (3 DTCs)

DTC	Description	Status
C1912	Tyre air pressure low, Tyre1	Stored DTC
C1931	Tyre ID reception fail, Tyre3	Active DTC
C1932	Tyre air pressure low, Tyre3	Stored DTC

Technician Notes

Customer Name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

